





HIETAKARI®




8/25 OKRLM


101




# Parts




1. x1




2. 6x30 mm  
x5




3. 4.5x44 mm  
x5




4. x1




5. 4.2x13 mm  
x4



6. x4




7. x1



8. x1




9. x1




10. x1


# Tools




A




Ø5 mm  
Ø6 mm  
B




C – Silicone








D




E








1





2



3




4



9

10



9

10